

Lucrari Planificate zilnic Sector Canal – 3 Aprilie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	DEFECT	56rao Mierlut C	Daraban L ,Daraban G		Teh.Patcas A
2	Vladeasa ,Ursului,Mimozei - curatat GS	66 rao Popovici	Bara,Teodoru ,Gal,		Teh.Patcas A
3	Gradinarilor, PC 39 -curatat CM Lapusului - curatat GS	29 rao Balaj I	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Gradinarilor - curatat CM	BH-83-RAO-Lucaciu	Paul A	Reclamatie consumator	Ing Coldea E
2	Mimozei 26 - curatat CM +GS	BH-13 CAO-Craciun	Buzas D	Reclamatie consumator	Ing Coldea E
3	Vladeasa , Ursului curatat GS + CM	BH-72-RAO-Tautu	Marchis	Reclamatie ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Mimozei 26 -vid retea menaj	BH-54-RAO-Muresan	Lazau Cicas	Reclamatie consumatr	Ing Coldea E
2	Gradinarilor,Calea Aradului,Calea Santandreiului,Kogalniceanu,Costaforu -vid retea menaj	BH-09- Ban	Balas	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Mimozei 24-26	38 rao	Rep canal colector menajer+ CP	Temciuc ,Burca,Budureanu,Sala Sziskai	ing.Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
----------------	---------------	---------------	------------------------------	------------------	-----------------

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Odobescu –stradal - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Muzeului 9,Saprtacus,Dacia AN 56 - curatat CM	BH-12-Duma	Derecichei Fuzi	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Fagului D67	45 rao	Rep canal menaj	Ciarnau, Groza	Ms.Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
1	I.C.Bratianu 54	45 rao	Refacere cu beton	Oros	Ms.Hamza
2	Ana Ipatescu 19/A	45 rao	Refacere cu beton	Uivarosi	Ms.Hamza