

**Lucrari Planificate zilnic de la Sector Canal**  
**Data: 20.04.2012**

## MAL STANG

### Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari,N.Bolcas,Fluierasului - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Sifonari,Calarasilor,Tuberozelor -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Ep Ioan Suciu,Lacul Rosu,Al Odobescu- curatat GS	29 rao Balaj I	Nagy, Demian		Teh.Patcas A

### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Gr Moisil,Nufarul,Centru Civic,A6-A10 - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Alex.Andritoiu,PB20-PB13 D 23-D21,Taberi Geza - curatat CM	BH-13 CAO-Vidican	Bohos	Reclamatie consumator	Ing.Coldea E
3	Cazaban S80,Vladeasa PB9,N.Bolcas - curatat CM	BH-72-RAO-Tautu	Marchis	Reclamatie ,consumator	Ing Coldea E

### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

<b>Nr crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
1	Nufarul,Gr Moisil, Kogalniceanu,Costaforu,S.M.Klein ,Centrul Civic A6-A10 -vid retea menaj	BH-54-RAO-Muresan	Cicas	Reclamatie consumatr	Ing Coldea E
2	Calea Santandreiului, Al .Rogerius,Pop de Basesti -vid retea menaj	BH-09- Zglibolt	Lazar	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

<b>Nr .</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Lanului 1	45 rao	Rep cacal col menaj	Sala ,Sziskai	Ing Coldea E
2	Al Andritoiu PB20-21,23	45 rao	Curatat CM	Budureanu	Ing Coldea E
3	Coziei 11	45 rao	Utilitati	Burca	Ing Coldea E

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

<b>Nr crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**f. Refacere cu beton**

<b>Nr. crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
----------------	---------------	---------------	------------------------------	------------------	-----------------

## **MAL DREPT**

**b)Desfundat canale :**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
1	Spitalului,Italiana - curatat /suflat GS	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta

2	M.Eminescu 11DGST-taxare,Macinului 32, C.Coposu - curatat CM	BH-12-Demian	Ciarnau	Reclamatie consumator	Ing Bonta
---	--	--------------	---------	-----------------------	-----------

**c)Lucrari de reparatii canalizare menajera,camine,**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Crivatului/Apelor	45 rao	Intubat sant	Fuzi , Groza	ms.Hamza
2	Macinuli 32	45 rao	Repcanal col menajer	Groza	ms.Hamza

**Reparati racord pluvial ,guri de scurgere –retea pluviala**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**e.Refacere cu beton**

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
1	Frunzei 4 -2	45 rao	Refacere cu beton	Oros Uivarosi	ms.Hamza