

Lucrari Planificate zilnic de la Sector Canal – 25 Aprilie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Lazar Gh.Mioritei,Satelitului,Simion St,N.Titulescu, - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Fabricilor,Sf Ladislau,P-ta Magnoliei,Minerilor,Savinestilor -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Stana de Vale,Gh,Marinescu,Macinului,Malului - curatat GS	29 rao Patcas	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Grigore Moisil, Nufarul ,Bumbacului,M.Eliade - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Crisan46,Dr Voda P1-P3,PB 26- PB 31 - curatat CM	BH-13 CAO-Craciun	Buzas	Reclamatie consumator	Ing.Coldea E
3	Mestesugarilor 27/A,GS,Vladeasa - curatat CM	BH-72-RAO-Tautu	Marchis	Reclamatie ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	T.Vladimirescu,Coziei,Costaforui -vid retea menaj	BH-54-RAO-Silaghi I	Cicas	Reclamatie consumatr	Ing Coldea E
2	Calea Santandrei,Calea Aradului,C.Coposu,Al Rogerius -vid retea menaj	BH-09- Ban	Balas	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Coziei 14	45 rao	Rep rac menaj+montat camin	Sala ,Sziskai, Budureanu,Burca	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Corneliu Coposu +cvartal bl AN17-an27 - curatat /suflat GS	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	G.Enescu 4,Al Odobescu PB 85-88 - curatat CM	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Corneliu Coposu AN27/B	45 rao	Repcanal canal colector menajer	Fuzi , Oros	ms.Hamza
2	Eroul Necunoscut /Pacii	45 rao	Montat rigole –fantana arteziana	Groza, Uivarosi, Sav	ms.Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------