

Lucrari Planificate zilnic de la Sector Canal – 12 iulie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Mihai Viteazu,C-tin Tanase -curatat GS	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Prutului,Scoalelor,Somesului -curatat GS	66 rao Popovici	Bara, Gal		Teh.Patcas A
3	Vaporului,Viorelelor,Closca 16-18 -curatat GS	45rao Silaghi	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sanmartin - curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Morii B60,Closca 16-18,Liszt Ferencz SH 875- curatat CM/GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing.Coldea E
3	B.St Delavrancea 12,Spartacus -tvs- curatat CM/GS	BH-72-RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Cicero,Costaforu,Kogalniceanu, Morii B60,Simion B29,Arany Ianos 2-vid retea menaj /pluviala	BH-54-RAO-Muresan	Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului,Spartacus –tvs, B.St Delavrancea 12 -vid retea menaj/pluviala	BH-O9- Ban	Popa	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Clujului 211	38.rao	Rep camin vizit	Budureanu,	Ing Coldea E
2	Tileagdului 31	38.rao	Rep camin vizit	Burca	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Closca 16-18	38.rao	Rep gura scurgere	Buzas	Ing Coldea E
2	Simion Barnutiu 24 PB 10	38.rao	Rep gura scurgere	Iuhasz	Ing Coldea E

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

MAL DREPT**a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Slatinei PB 21,Doina PB 96 - curatat GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta
2	DEFECT	BH -73 RAO			
3	DEFECT	BH -71 RAO			

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Spartacus –tvs	38 rao	Rep camin vizitare	Ciarnau .Groza	Ing Bonta
2	G.Calinescu AN 47	38 rao	Rep camin vizitare	Sav	Ing Bonta
3	Sovata C2-C3	38 rao	Rep camin vizitare	Buzas, Toie	Ing Bonta

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------