

## Lucrari Planificate zilnic de la Sector Canal – 19 iulie 2012

### MAL STANG

#### a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari,Liszt Ferencz-curatat GS	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Sifonari,C-tin Noica -curatat GS	66 rao Popovici	Gal ,Teodoru		Teh.Patcas A
3	Iasomieii,Albacului,Nufarul27/C,St cel Mare AN 41-42,b.Show C5-curatat GS/CM	45rao Silaghi	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sanmartin,Nufarul AN 41-42- curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Tr Mosoiu 19,Vaporului 21,Ov Densusanu, - curatat CM/GS	BH-13 CAO-Silaghi	Marchis	Reclamatie consumator	Ing.Coldea E
3	Borsului –parc industrial-Taxare	BH-72-RAO- Tautu	Bernat	Reclamatie consumator	Ing Coldea E

#### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Hategului/Pionerilor,,Costaforu,Cicero,Kogalniceanu,Uzinelor	BH-54-RAO-Muresan	Cicas Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului, Cicero,Santului,B Show,Razboieni-vid retea menaj/pluviala	BH-09- Zglibolt	Lazar	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

<b>Nr.</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Razboieni /Caprioarei	45 rao	Rid la cota cm	Ciarnau Uivarosi ,Groza	Zetocha

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

<b>Nr crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Razboieni /Caprioarei	45 rao	Rep canal plv	Balas,Iuhasz,Burca	Zetocha
2	Pompei 5	45 rao	Rep gs		Zetocha

**f. Refacere cu beton**

<b>Nr. crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Pitestilor 10	45 rao	Refacere cu beton	Burca	Zetocha

**MAL DREPT****a)Desfundat canale :**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
2	St cel Mare Can 41-42,B.Show C5 Dacua U1 - curatat GS/CM	BH-12-Demian	Fuzi	Reclamatie consumator	Ing Bonta

**b) Lucrari de reparatii canalizare menajera, camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Sovata C2- C3	45 roa	Rid la cota cm	Ciarnau, Groza	Ing Bonta

**c) Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**d) Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	--------------------------	------------------	-----------------