

Lucrari Planificate zilnic de la Sector Canal

Data: 24.07.2012

MAL STANG

Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Dacia -curatat GS Meziadului/ErGrigore,Progresului/Carpati,Stelutei,W.Sheakespeare/RER ridicat mizerie CM	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Cvartal Dacia -curatat GS	66 rao Popovici	Gal ,Teodoru		Teh.Patcas A
3	Lucrari	45rao Urs C	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Morii x8,Timotei Cipariu 41,Liszt F/Leonardo da Vinci- curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Andritoiu.Oct Goga,Paleului - curatat CM/GS	BH-13 CAO-Craciun	Marchis	Reclamatie consumator	Ing.Coldea E
3	Carasului,Costaforu/22Decembrie,Gr Ureche- curatat CM/GS	BH-72-RAO- Tautu	Bernat	Reclamatie consumator	Ing Coldea E
4	Cvartal Dacia - curatat CM/GS	BH-43 –RAO-Chisvasi	Rotaru	Reclamatie consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Liber	BH-54-RAO-Muresan		Reclamatie consumatr	Ing Coldea E
2	TINCA, Biruintei 6 –taxare -vid retea menaj/pluviala	BH-09- Ban	Popa	Reclamatie consumator	Ing Coldea E
3	Cicero,Costaforu,Kogalniceanu,Uzinelir-Retea	BH-71-RAO-Tartea	Cicas,Lazau	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Fluierasului 11	45 rao	Rep rac .menaj	Budureanu,Buzas,Burca	Zetocha

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	M.Viteazu/Kogalniceanu	45 rao	Rep gura scurgere	Bohos,Iuhasz	Zetocha

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Costaforu 50	45 rao	Refacere cu beton	Balas,	Zetocha

MAL DREPT

b)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
---------------	---------------	---------------	------------------	----------------------	-----------------

2	Er Necunoscut, Odobescu, Doina - curatat GS/CM	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta
---	--	------------	------------	-----------------------	-----------

c) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Sovata C2- C3	45 rao	Rid la cota cm	Ciarnau, Groza, Uivarosi	Ing Bonta

Reparati racord pluvial ,guri de scurgere –retea pluviala 45 rao

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Republicii 10	45 roa	Rep rac pluvial	Buzas, Toie ,Sav	Ing Bonta

e. Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
--------	--------	--------	-------------------	-----------	----------