

Lucrari Planificate zilnic de la Sector Canal – 03 Mai 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Calea Aradului,cvartal bl Calea Aradului - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Averescu,cvartal bl Averescu -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Ioan Cantacuzino - curatat GS	29 rao Balaj I	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Razboieni,Brandusei, - curatat CM Averescu - curatat GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	DEFECT	BH-13 CAO-		Reclamatie consumator	Ing.Coldea E
3	Jokai Morr,P.Ispirescu,Crisan/Feldioarei,Aurel Lazar - curatat CM Calea Aradului -- curatat GS	BH-72-RAO-MC	Temciuc	Reclamatie ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Av Iancu,P Ispirescu,Costaforu,Kogalniceanu,Crisan /Feldioarei - vid retea menaj	BH-54-RAO-Silaghi	Cicas	Reclamatie consumatr	Ing Coldea E
2	Calea AraduluiCalea Santandrei,Crisan/Feldioarei,Pop de Basesti-vid retea menaj	BH-09- Urs	Balas	Reclamatie consumator	Ing Coldea E
3	Bumbacului,Clujului	BH-43- RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

N r.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Avram Iancu 5	38 rao	Rep rac menaj	Sziskai, Sala,Budureanu,Iuhasz	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

Sef Mal Sting: **ing Coldea Eugen****MAL DREPT****a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Dacia C5-C7,C.Negruzi,Doinei - curatat /suflat GS/CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Al Rogerius,Cantacuzino - curatat CM/GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

b)Lucrari de reparatii canalizare menajera,camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Renasterii 29	38 rao	Rep rac menaj	Oros, Uivarosi,Toie	ms.Hamza

c)Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Calugareni V6	38 rao	Rep gura scurgere	Sav,Groza	ms.Hamza
2	Iasomieii /Lamaitei	38 rao	Rep gura scurgere	Buzas	ms.Hamza

d)Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------