

Lucrari Planificate zilnic de la Sector Canal

MAL STANG

Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari,Ghioceilor,P-ta Ghioceilor - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Sifonari,Hategului -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Gradinarilor,cvartal bl Gradinarilor	29 rao Balaj I	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	T.Vladimirescu ,Gradinarilor - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	DEFECT	BH-13 CAO-		Reclamatie consumator	Ing.Coldea E
3	Splaiul Crisanei ,Lapusului - curatat CM/GS	BH-72-RAO-Mierlut C	Temciuc	Reclamatie ,consumator	Ing Coldea E

c. Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Kogalniceanu, Pop de Basesti, T. Vladimirescu 24, Costaforu, St Oct Iosif, Xenopol , H. Coanda -vid retea menaj	BH-54-RAO-Silaghi	Cicas	Reclamatie consumatr	Ing Coldea E
2	Calea Santandreiului, Al .Rogerius, Calea Aradului -vid retea menaj	BH-09-RAO - Urs	Lazar	Reclamatie consumator	Ing Coldea E
3	Hategului, -gs ; Xenopol, H. Coanda- CM	BH-43 –RAO -Tautu	Iuhasz	Reclamatie consumator	Ing Coldea E

d. Lucrari de reparatii canalizare menajera ,colector menajer, si camine de vizitare:

N r.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Petre Ispirescu PB 42	38 rao	Rep camin menajer	Sziskai, Sala	Ing Coldea E
2	Xenopol , Henri Coanda	38 rao	Curatat retea /camine menaj	Budureanu ,Burca	Ing Coldea E

e. Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
----------------	---------------	---------------	------------------------------	------------------	-----------------

MAL DREPT

b) Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sf Ap Andrei, D19-20, sSovata PB43-35, D 30-32 - curatat /suflat GS/CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Galileo Galilei - curatat CM/GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

c) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Raspantiilor 29	45 rao	Rep rac menaj	Oros, Uivarosi, Toie	ms.Hamza
2	Calugareni C 2	45 rao	Rep rac menaj	Sav ,Buzas, Groza	ms.Hamza

Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

e. Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
--------	--------	--------	-------------------	-----------	----------