

Lucrari Planificate zilnic de la Sector Canal – 31 Mai 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Matei Corvin - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Matei Corvin -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Pelicanului,Inului,Harghitei,Ciucului - curatat GS	29 rao Silaghi	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Averescu 45,Universitatii, - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	DEFECT	BH-13 CAO-		Reclamatie consumator	Ing.Coldea E
3	B-dul Decebal - curatat CM/ GS	BH-72-RAO-Mierlut C	Temciuc	Reclamatie consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	,Kogalniceanu, Costaforu,Pop de Basest,Selesulului-vid retea menaj	BH-54-RAO-Muresan	Cicas	Reclamatie consumatr	Ing Coldea E
2	Ady Endre 46, Calea Aradului ,Calea Santandrei.,Pascal DP 72-vid retea menaj	BH-09- Urs	Popa	Reclamatie consumator	Ing Coldea E
3	Matei Corvin - suflat GS Averescu 45,Splaiul Crisanei –curatat CM	BH-43- RAO-Tautu	Bernat	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

N r.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Averescu 45	38 rao	Rep rac menaj	Sala ,Sziskai, Iuhasz	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Banatului PB 3	38 rao	Ref cu beton	Bohos ,Burca, ,Buzas	Ing Coldea E

Sef Mal Sting: **ing Coldea Eugen**

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	B-dul Decebal - curatat/suflat GS	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Ady Endre 46- curatat CM/GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	T.Vladimirescu 60 /A	38 rao	Rep rac menaj	Oros ,Groza,Uivarosi	ms.Hamza
2	Dacia AN 52	38 rao	Completat capace furate	Toie Buzas	ms.Hamza
3	Savinestilor 24	38 rao	Completat capace furate	Sav	ms.Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------