

Lucrari Planificate zilnic de la Sector Canal – 14 Martie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Jean Jaurez,Lugojului,Dobrogei -curatat GS	56 rao	Daraban L ,Daraban G		Teh.Patcas A
2	Eforiei,Mierlei,Morii,Otelarilor - curatat GS	66 rao	Teodoru.Bara		Teh.Patcas A
3	Arany Ianos,Crisului,Galileo Galilei — curatat GS	29 rao	Naghi,Demian		Teh.Patcas A
4	Coziei, Vaida Voievod Marasti Mociulski,Gradinarilor x1-curatat CM	38 rao	Bohos,Iuhasz		Ing.Coldea

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Coziei,Marasti,Al,Vaida Voievod - curatat CM	BH-83-RAO-Lucaciu	Paul V Paul A	Reclamatie consumator	Ing Coldea E
2	Borsecului x14-x17z1-z2,Armatai Romane sediul NATO - curatat CM	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing Coldea E
3	Sf Apostol Andrei PC 42-44,Seleusului D43-50 - curatat CM	BH-72-RAO-Tautu	Bernat	Reclamati ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Kostafor,Cogalniceanu,Coziei,Marasti,Vaida Voievod, Mociulski ,Calea Santandrei -vid retea menaj	BH-54-RAO-Muresan	Cicas, Lazau	Reclamatie consumatr	Ing Coldea E
2	Statia de Epurare Oradea -vid retea menaj	BH-09- Ban	Popa R	Reclamati consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Atelierelor 9/A	38 rao	Rep canal menaj	Sala ,Sziskai	Ing Coldea

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Aviatorilor 119		Rep guras curgere	Budureanu,Balas	Ing Coldea E

f.Refacere pavaje lucrari

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

Sef Mal Sting: **ing Coldea Eugen**

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Dacia C7,Gh Doje 22-24 - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Republicii 11,Statia de Epurare Oradea	BH-12-Duma	Fuzi	Reclamatie consumator	Ing Bonta

b)Lucrari de reparatii canalizare menajera,camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Dacia C7	45 rao	Curatat/periat -CM	Toie, Derecichei	Ms Hamza
2	Sf.Apostol Andrei	45 rao	Curatat/periat -CM	Uivarosi,Buzas,	Ms Hamza

3	Gh Doja 22-26	45 rao	Curatat/periat -CM	Sav Ciarnau	Ms Hamza
----------	----------------------	---------------	---------------------------	--------------------	-----------------

c)Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d)Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------

e)BLINDARI :Canal menajer pentru neplata