

Lucrari Planificate zilnic de la Sector Canal – 30 Martie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Drum CET 2 ,Sifonari -curatat GS	56rao Mierlut C	Daraban L ,Daraban G		Teh.Patcas A
2	Calea Santandreiului,Al Rogerius - curatat GS	66 rao Popovici	Bara,Teodoru ,Gal,		Teh.Patcas A
3	Calea Santandreiului ,Aleea Rogerius G4-G6.E1 –E 2 -curatat CM	29 rao Silaghi	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Scoalelor,Mimozei- curatat CM	BH-83-RAO-Lucaciu	Paul V Paul A	Reclamatie consumator	Ing Coldea E
2	Oct Goga,Calea Aradului- curatat CM +GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing Coldea E
3	Cazaban,Onestilor,H.Coanda Clujului - curatat GS + CM	BH-72-RAO-Tautu	Bernat	Reclamati ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Calea Santandreiului,Calea Aradului,Oradea Center,Mimozei,Kogalniceanu -vid retea menaj	BH-54-RAO-Muresan	Lazau	Reclamatie consumatr	Ing Coldea E
2	Olteniei 22-24,Al Rogerius L1L2L2-G6 Sovata Q2 -vid retea menaj	BH-09- Ban	Lazar	Reclamati consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
------	--------	--------	-----------------------	-----------	----------

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1*	Lugojului/Beiusului	38 rao	Refacere cu beton	Sala Sziskai,Burca	Ing.Zetocha

Sef Mal Sting: **ing Coldea Eugen**

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	C.Coposu,Odobescu, - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Alea Rogerius L1L2L23-G6,Cantonului Republicii - curatat CM	BH-12-Duma	Fuzi	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Al Odobescu PB 83	45 rao	Rep camin vizitare	Toie Groza Uivarosi	Ing Bonta
2	Al Odobescu PB 84	45 rao	Rep camin vizitare	Derecichei ,Buzas	Ing Bonta
3	Mimozei 23	45 rao	Rep rac menaj	Burca Balas Bohos	Ing Bonta

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------