

Lucrari Planificate zilnic de la Sector Canal – 22 Octombrie 2012

a. Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Defect - curatat G.S	56rao-lipsa sofer			Teh.Patcas
2	Defect -curatat G.S	66rao –PP -Bolnav			Teh.Patcas
3	- curatat G.S	45rao-Ungur	Demian,Gal , Teodoru		Teh.Patcas
4	Eroul Necunoscut-biserica reformata- Lucrare	BH-			

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	TINCA –curatat retea cm /gs	BH-83-RAO-Lucaci	Paul V	Populatia + conducere	Ing Coldea
2	Defect	BH-13 CAO-		Populatia + conducere	Ing Coldea
3	T.Cipariu 26/A,Andritoiu PB 28-PC 29,Privighetorii 3,Al Zidarilor Z4,1907,Sabelor 21,Liszt Ferencz/Leonardo da Vinci,Gr Moisil - curatat retea cm /gs	BH-72-RAO- Craciun	Temciuc	Populatia + conducere	Ing Coldea
4	Aleea Calinului - curatat retea cm /gs	BH-43-RAO- Chisvasi	Bernat	Populatia + conducere	Ing Coldea

c.Vidanjat retea canalizare menajera si pluviala(lucrari

Nr crt	Strada	Masini	Muncitor	Cine solicita	Raspunde
1	Costaforu,Cicero,C.Sintandrei, Kogalniceanu 3,Calea Aradului,Calea Santandreiului,1907 nr 22,Timotei Cipariu 26/A , -vidanjat retea cm/cp	BH-54-RAO-Muresan	Burca	Populatia+conducere	IngColdea
2	Gh Doja 129,Santului,Calea Aradului,Al Rogerius,Aleea Calinului -vidanjat retea cm/cp	BH-09- Ban	Balas P		Ing Bonta

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	1907 nr 22	38 rao	Rep rac menajer	Sziskai,Sala	Ing Zetocha
2	Ialomitei AN 7	38 rao	Completat capac camin	Budureanu, Sala	Ing Zetocha

e.Rep racord pluvial si Guri de scurgere

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

f.Refacere pavaje lucrari

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
----------------	---------------	---------------	------------------------------	------------------	-----------------

g)Curatat canal menajer

Nr.crt	Nume prenume, adresa	Masini	Muncitori	Cine solicita	Raspunde
---------------	-----------------------------	---------------	------------------	----------------------	-----------------

MAL DREPT:**a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	St cel Mare D 63, St cel Mare AN 41-42,Sf Apostol Andrei D19-D20,Decebal B 52-51 - curatat- periat cm/gs		BH-12- Demian	Derecichei	Ing Bonta

b) Lucrari de reparatii canalizare menajer, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Eroul Necunoscut –biserica reformata	38rao/22rao	Montat camin +rac menaj	Groza, Sav	ing.Silaghi
2	C.Brancus 6	22rao	Completat capac lipsa cm	Ciarnau, Toie	ing.Silaghi
3	Fagetului	22rao	Completat capac lipsa cm	Oros ,Rotaru	ing.Silaghi

c) Reparati racord pluvial si G.S

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d. Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------

e) BLINDARI Canal menajer pentru neplata