

## Lucrari Planificate zilnic de la Sector Canal – 16 Mai 2013

**MAL STANG**  
**ing Coldea Eugen**

### A) Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Fagarasului 110,Salcamilor X161-180 -Lucrari	45 RAO-Urs			
2	P-ta Independentei,A10,Prutului D13,Somesului D62,-cm /Seleusului -gs - curatat	66-RAO-Popovici	Gal, Bara		ing Coldea
3	Calea Clujului –curatat gs	29 RAO-Bodea	Demian,Teodoru,		ing Coldea

### B) Desfundat canale

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Prutului D13,Somesului D62,Razboieni PB 1,2,Splaiul Crisanei,Poianitei	BH-83RAO-Lucaci	Paul V	Reclam./Dispecerat	ing Coldea
2	Calea Clujului,Aleea Gojdu9,P-ta Independentei A10 – curatat cm/gs	BH-13 CAO-Cracium	Temciuc	Reclam./Dispecerat	ing Coldea

### C) Vidanjat retea canalizare menajera si pluviala( lucrari)

Nr crt	Strada	Masini	Muncitor	Cine solicita	Raspunde
1	Seleusului,Al Rogerius,Santului,Costaforu,Razboieni T2,Salcamilor X161-180,Cicero,-Betfia 82,Ogorului 37/C,p-TA Independentei A10-vidanjat reta cm/cp	54 RAO-Ban	Popa R	Reclam./Dispecerat	ing Coldea

**D) Lucrari de reparatii la canalizarea menajera -colector menajer,camine de vizitare,racorduri menajere:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Salcamilor X179-180-161	23 rao+or 300 Coman	Rep canal colector menaj	Buzas,Bohos,Bernat,Iuhasz,	ing Coldea`
2	E.Gojdu 9	23 rao	Rep racord menajer	Cicas,Sala Sziskai,	ing Coldea`

**E) Rep racord pluvial si Guri de scurgere**

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Fagarasului 110	23 rao+2143-Chirila	Rep canal colector plv	Cicas,Sala Sziskai,	ing Coldea`

**F) Refacere pavaje lucrari**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

**G) BLINDARI Canal menajer pentru neplata:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
------	--------	--------	-----------------------	-----------	----------

**MAL.DREPT:**  
**ing. Dumitru BONTA**

**A)Curatat Guri de scurgere/camin menajer**

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Academiei 10,Ady Endre 70 – Lucrare	38 RAO-Muresan			ing.Bonta
2	Calea Clujului –curatat gs	29 RAO-Bodea	Bara A, Demian,Teodoru,		ing.Bonta

**B) Desfundat canale**

Nr.	Strada	Masini	Muncitori	Cine solicita	Raspunde
-----	--------	--------	-----------	---------------	----------

cr					
1	Academiei 10,DaciaC5.C7,Negruzi,Balcescu,Brancus- curatat cm/gs	BH-12-Duma	Derecichei	Reclam./Dispecer	ing.Bonta
2	Th Sperantia PB 15,I C Bratianu ,Anton Pan 3,Sf Apostol Andrei -- curatat cm/gs	BH-73-RAO-Chisvasi	Rotaru	Reclam./Dispecer	ing.Bonta

**C) Lucrari de reparatii la canalizarea menajera -colector menajer,camine de vizitare,racorduri menajere:**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
--------	--------	--------	-----------------------	-----------	-----------

**D) Reparati racord pluvial si G.S**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Academiei 10	22 RAO	Rep rac pluvial	Sav, Ciarnau, Uivarosi	ing, Silaghi

**4E) Refacere cu beton**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Ady Endre 70	22 RAO	Ref cu beton	Toie ,Paul,Groza,Rotaru	ing, Silaghi

**F) BLINDARI Canal menajer pentru neplata**