

## Lucrari Planificate zilnic de la Sector Canal - 08.03.2013

**MAL STANG**  
ing Coldea Eugen

### a) Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	P.Curcanu; XR16,O.Ghibu X16 ,Ardealului ,P.Curcanul - curatat cm/gs	66 RAO-Popovici	Demian,Bara,	Curatat gs cm	ing Coldea
2	Er Necunoscut,Republicii,Flamarioe Pc 63 -Lucrari	38-RAO-Coita	Paul A		ing, Silaghi
3	Sifonari,P-ta Cazarmi,Rosiorilor,Al ZidarilorZ1A.Z1B.Z1C	45 –RAO-Ciki	Teodoru,Daraban L		ing Coldea
4	Sifonari,T.Lalescu cvartel bl T.Lalescu	29-RAO-Bodea	Daraban G		ing Coldea

### b) Desfundat canale

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Poienitei 22-24,O.Ghibu x16,Bumbacului M 52-56,Morii - curatat cm/gs	BH-83RAO-Lucaci	Paul,Balaj	Reclamatie/ Dispecerat	ing Coldea
2	P-ta Cazarmii /Rosiorilor,Zarandului,Marasti 10- curatat cm/gs	BH-13 CAO-Silaghi	Marchis	Reclamatie/ Dispecerat	ing Coldea
3	Al Zidarilor ,C.Noica dn4,Ialomitei AN 2-7,Mediasului 20,Brasovului 25 - curatat cm/gs	BH-72RAO-Tautu	Bernat,Fuzi	Reclamatie/ Dispecerat	ing Coldea
4	Transilvaniei –gs,Flamarion-cm T.Lalescu -gs	BH-73RAO-Chisvasi	Rotaru,	Reclamatie/ Dispecerat	ing Coldea

**c) Vidanjat retea canalizare menajera si pluviala( lucrari)**

Nr crt	Strada	Masini	Muncitor	Cine solicita	Raspunde
1	C.Aradulu,C.Santandreiului,Al Rogerius,Santului, Kogalniceanu ,Costaforu, - vidanjat reta cm/cp	54 RAO-Muresan	Popa	Reclamatie /Dispecerat	ing Coldea
2	<b>DEFECT</b>	<b>BH-09- CAO ,</b>		Reclamatie /Dispecerat	ing Coldea
3	,Razboieni 13/A,Cicero,Costaforu,Kogalniceanu,Al Zidarilor Z1A,Z1C,Z1B - vidanjat reta cm/cp	71 RAO-Tartea	Iuhasz	Reclamatie /Dispecerat	ing Coldea

**d) Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Onisifor Ghibu x16	23 rao+ 45 rao	Rep canal colector	Sziskai,Sala,	ing Coldea
2	Penes Curcanul R16-X20	23 rao+ 45 rao	Rep camin vizitare	Bohos	ing Coldea`
3	Cazaban P5 P6	23 rao+ 45 rao	Rep camin vizitare	Cicas	ing Coldea`

**e) Rep racord pluvial si Guri de scurgere**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
					,

**f) Refacere pavaje lucrari**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde

**g) Curatat canal menajer**

Nr. crt	Nume prenume, adresa	Masini	Muncitori	Cine solicita	Raspunde

**MAL.DREPT:**  
**ing. Dumitru BONTA**

**a) Desfundat canale**

<b>Nr.cr</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
1	Dacia C5-C6,b,Show x6-x8 C5-C7,Odobescu PC 83-85	BH-12- Demian	Buzas	Reclamatie /Dispecerat	Ing Bonta

**b) Lucrari de reparatii canalizare menajer,camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Flamaroin PC 63	22 rao+38 rao	Rep camin vizitare	Ciarnau ,Sav	ing, Silaghi
2	Er Necunoscut –Biserica reformata	22 rao+38 rao	Ref camin vizitare	Oros,Groza	ing, Silaghi
3	Republicii 51	22 rao+38 rao	Ref cu pamant	Fuzi,Toie,Paul	ing, Silaghi

**c) Reparati racord pluvial si G.S**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**d) Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**e) BLINDARI Canal menajer pentru neplata**